LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC CO. 5 CORNERS

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1
I. PUBLIC LAND SURVEY	T S., R E.		
2. PROPERTY CONTROLL-24	T. 44 故 R. 7 V	5, 6, 9	
3. MISCELLANEOUS PROPERTY IN SECTION		****	
4. LOT NO , RECOR	RDED PLAT		
5. PRIVATE CLAIMS		·. <u></u> -	REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re-mand rules therefore as required in Bureau of Land Management or band 5 above were, in a field survey	onumented, recovered or re- the current manual of surve y a decree of a court of law.	stored as expressed below an y instructions of the United Furthermore, that the corn 19, found, recovered, re	of P.A. 74, Michigan P.A. of 1970, 1987, established, d in conformance with regulations States Department of the Interior, er points mentioned in lines 3, 4 stored, established or re-established stration for Land Surveyors or, by a
A. Description of original monum	ent and accessories and/or s	ubsequent restoration:	ı
North 1/16 Corner of Sec	ction 24. Set by my	self on 8-31-87.	
N.E. 1/16 Corner of Sec	tion 24. Set by mys	elf on \$-31-87.	
East 1/16 Corner of Sec	tion 14. Set by mys	elf on 8-31-87.	
B. Description of corner evidence This record is a correct This record is a correct This record is a correct	tion of record dated tion of record dated	! 9-22-87. ! 9-22-87.	
8" Balsam, S31°W, 82.80 8" Balsam, S66°E, 87.10 8" Spruce, S6°E, 90.85 8" Balsam, North, 51.20	' 6 10" Ironwood, ' 10" H. Maple.	N57°W, 24.20' 9 S79°W, 9.92' N74°E, 20.70'	ne position of the corner: 6" Cedar, S32°E, 9.8' 6" Cedar, S45°W, 11.5' 6" Cedar, N21°W, 6.7' 6" Cedar, N52°E, 3.9'
SIGNED BY Gerald L. W. SURVEYOR'S MICHIGAN REGI		DATE_2-3-	GERALD L. WIGGINS LAND LAND SURVEYOR No.
FOR STATE AND UNITED STA	TES AGENCIES:		23521
SIGNED BY	CHIEF OF EURYEY PARTY	DATE	LAND
APPROVED AND SIGNED BY_		NO SURVEYOR	(SEAL)
SURVEYOR'S MICHIGAN REGI	STRATION NO		