

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 8 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 28 and 29

CORNER MONUMENT 3/8" x 24" Iron Bar (buried in road)

DATE MONUMENT PLACED AND WITNESSED 9/2/60

WITNESSES TO CORNER.....6" Elm (1/4s NBT) S 72° E 81 1/4 Links



6" S. Maple (1/4s NBT) S 81° W 75 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners.
Placed location poster 50 Links west. Corner lies 97 links south of south edge
of clearing on west side of road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 5/25/61
REGISTERED LAND SURVEYOR
Billy D. Buckler