

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 8 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 8 and 9

CORNER MONUMENT 3/8" x 24" Iron Bar (buried in road)

DATE MONUMENT PLACED AND WITNESSED 9/2/60

WITNESSES TO CORNER.....6" Cedar (1/4s NBT) N 56° E 46 1/2 Links



7" Cedar (1/4s NBT) N 82° W 53 1/4 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners.

Placed location poster 50 Links west of corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 5/25/61
REGISTERED LAND SURVEYOR
Billy D. Buckler