

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 44N R 8W

DESCRIPTION OF CORNER ½ Cor. bet. Secs. 5-6

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9-19-68

WITNESSES TO CORNER..... 14" Hard Maple (½ S NBT) N18°E 42.0'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 31.0' north of approx LC E-W road and 12' west of pine plantation edge.

This corner re-established by simple proportionate measure bet. a Sec. Cor. to south and a closing corner to north. No evidence of original Cor.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

4-4-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68