## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

			Mackinas	COUNTY
		T	44N	R
DESCRIPTION OF CORNER	Sec. Cor. commen to Secs	. 22-23-26-	-27	
CORNER MONUMENT 10 p	ipe with 4" aluminum cap.			
DATE MONUMENT PLACED A	ND WITNESSED 9-25-68			
WITNESSES TO CORNER	4" W. Pine (S23 NBT)	N50 <sup>®</sup> E 61.61	!	
N	A" Tamarack S27 NBT)	831 <b>%</b> 10.8		
27	:			
	AND			
CIRCLE CORNER REGIST	ERED		· · ·	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in an open marsh, 60° SW of a lew ridge.

This corner replaced as set by an unknown surveyor. Found an old squared post of indefinite age with a picket line to east and west. Distance north to marsh and swamp edge check as well as distance south to a small pond. Found no evidence of eriginal spruce witnesses.

SURVEYOR'S SEAL

SIGNED

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68