STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | | M | Mackinas | | COUNTY | |
|-------------------------|---|--------------------|--------------------|----------|---------|--|
| | | τ_ | 44N | R _ | 8W | |
| DESCRIPTION OF CORNER | East 1/16 corner bet. Secs | . 15-22 | ··· - · | | <u></u> | |
| CORNER MONUMENT 1 P1 | pe with 4" aluminum cap. | | | | | |
| DATE MONUMENT PLACED AN | D WITNESSED 1-9-69 12" Red Pine (1/16 BT) N | 71 ° E 19.3 | | <u> </u> | | |
| N CORNER | 9" Red Pine (1/16 BT) S | | | | | |
| 22 | AND | | | | | |
| CIRCLE CORNER REGISTE | RED | | | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway bet. Sec. Cor. to east and $\frac{1}{4}$ cor. to west. Cerner lies 30° west of east edge of pine plantation.

SURVEYOR'S SEAL

SIGNED

Willy & Buch

Billy D. Buckler

DATE 4-4-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing