

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 15-16-21-22

CORNER MONUMENT 1" pipe with 4" aluminum cap buried in old road.

DATE MONUMENT PLACED AND WITNESSED 9-27-68

WITNESSES TO CORNER..... 9" R. Pine (S15 NBT) N45°E 17.4'



9" R. Pine (S21 NBT) S30°W 10.9'

9" Jack Pine (S16 NBT) N19°W 16.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed by proportionate measure from corners one mile east and west;
one mile south and swamp edges to north.
No evidence of original cor.

Corner lies in an old road, bearing NW-SE.
Placed location post 4' north of cor.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

4-4-69

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing