

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 44N R 8W

DESCRIPTION OF CORNER West 1/16 corner, Sec. 6

CORNER MONUMENT 2" iron pipe in 8" concrete monument

DATE MONUMENT PLACED AND WITNESSED 4-1-68

WITNESSES TO CORNER..... 15" Elm (NBT) S75°W 33.9'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed monument as set by unknown surveyor.  
Cor. lies approx. in line with road to north and east.  
Fence corner bears S44°W 22.0'  
A fence further south lines with the corner.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

3-18-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing