STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	Mackina	COUNTY
	Т	R
DESCRIPTION OF CORNER Sec. Cor. common to Secs. 25-26	<u>-35-36</u>	
CORNER MONUMENT 1" pipe with 4" aluminum cap.	···	 .
DATE MONUMENT PLACED AND WITNESSED 5-8-68		
WITNESSES TO CORNER 6" Hard Maple (S35 NBT) S14%	32.41	
N C		
)		
35		
AND		
CIRCLE CORNER REGISTERED		_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced by extending a straight line from south through the ‡ corner and the north 1/16 cerner an equal distance.

Corner falls in line with eld fence line to north and proper distance south of marsh.

SURVEYOR'S SEAL

SIGNED

Silly & Suckles.
Billy D. Buckler

REGISTERED LAND SURVEYOR

3-20-69

DATE

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor

Forestry Div., Lansing