

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8W

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 35-36

CORNER MONUMENT 1 1/2" x 30" iron pipe, buried in N-S road

DATE MONUMENT PLACED AND WITNESSED 5-8-68

WITNESSES TO CORNER..... 12" Elm (NBT) N63°E 25.1'



11" J. Pine (NBT) S42°E 70.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Located this corner as set by unknown surveyor. Found iron pipe in center of N-S road and midway between fence corners.
Distance south to center of Section = 1319.6'

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 3-20-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68