

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 44N R 8W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 26-27-34-35

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5-8-68

WITNESSES TO CORNER..... 10" Hard Maple (S27 NBT) N82°W 18.7'



9" Hard Maple (S26 NBT) N17°E 8.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as recorded by Marcus Schaaf, R.L.S. Could not find Schaaf's corner but did find two random lines, which were run in 1937. Located corner from these lines.

Corner lies in hardwood, approx. 100' north of road.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

3-20-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68