

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Luce & Mackinac COUNTY


T 44-45N R 8W

DESCRIPTION OF CORNER 1/2 Cor. bet. Secs. 36-1

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-31-68

WITNESSES TO CORNER..... 12" Cedar (1/2 S NBT) S63°W 67.9'



9" Jack Pine (1/2 S NBT) S8°W 39.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

Corner lies in edge of swamp and 40' north of a pine plantation.

SURVEYOR'S SEAL

*Billy D. Buckler*

SIGNED

Billy D. Buckler

DATE 3-20-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68