

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac & Luce COUNTY


T 44N R 6W

DESCRIPTION OF CORNER 1/4 corner on north side Sec. 6

CORNER MONUMENT 2" iron pipe in 8" concrete monument

DATE MONUMENT PLACED AND WITNESSED 5-9-68

WITNESSES TO CORNER..... 5" Red Pine (NBT) S14°E 27.7'



14" Hard Maple clump (NBT) N20°E 40.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor.  
Found a 1/2" iron rod 12.2' west of this monument. W/old squared post on ground,  
appears to be the 1/4 corner for Sec. 31, to north.

Note:

This mile has double corners

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*

Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

3-18-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68