

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 25-36

CORNER MONUMENT 1 1/2" x 30" iron pipe

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... 8" Tamarack (NBT) N35°E 5.6'



3" cedar (NBT) S40°E 5.3'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced on an old N-S grade by extending a line, equal distance through a corner found; 1/4 mile south and 1/4 mile south.

Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-27-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing