

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44N N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 4 Cor. bet. Secs. 12-13

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-22-70

WITNESSES TO CORNER..... 12" Hard Maple (S NBT) N33°E 85.6'



9" Hard Maple (S NBT) N10°W 114.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced between two fence corners and in center of a fenced road, running north and south.

Found no evidence of original corner, but did find an original corner  $\frac{1}{2}$  mile west to fit well.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 12 2 70