LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Mackinac Co. Three Corners.

	ه آيي	C1 . + C	
FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SU	RVEY T S., R	8-Sec. 27	
2. PROPERTY CONTROLL- 27 ,T. 44 S., R. 8 W. 11-Sec. 27 12-Sec. 27			
3. MISCELLANEOUS N. E. PROPERTY IN SECTION, T			
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER			
I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 5-8 19.73, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration: 8-Sec.27 West 1/16 Corner.			
11-Sec.27 South-West 1/16 Corner.			
12-Sec.27 South 1/16 Corner.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 8-Sec.27 1/16 Corner placed, midway bet Cor. to West and Center Cor. to East. 11-Sec.27 Corner placed, at intersection of lines, quartering the South-West Quarter Section.			
12-Sec.27 Corner placed, midway bet. $\frac{1}{4}$ Cor. to South and Center Cor. to North.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe at all three Corners.			
8-Sec.27	Bearings: 8" Maple, N82	ow, 23.5' and 7" Map	le, N21°E, 25.6'
11-Sec.27	Bearings: 8" Maple, S66	⁰ W, 50.8' and 6" Map	le, S14°E, 27.1'
12-Sec.27	Bearings: 8" Maple, S27	OW, 17.1' and 7" Map	le, East, 19.3
SURVEYOR'S MIC	Billy D. Buckler CHIGAN REGISTRATION NO.	DATE	1/30/A BULLY DE PER SONO NO. 100 NO. 1
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF BURVEY PARTY	DATE	
APPROVED AND SIGNED BY MICHIEAN REGISTERED LAND SURVEYOR DATE			