

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 .. NR. .. S. .. W

M a s k i n s o .. COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 16, 17, 20, 21

DESCRIPTION OF CORNER MONUMENT 1/2" x 36" Iron Bar buried in center of road.

WITNESSES TO CORNER 7" B. Cherry .. S 72° E .. 59 Links

10" B. Cherry .. S 88° W .. 109 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by proportionate measure to North and South and in center of N-S road. Place location poster 50 links west.

Corner was placed and witnessed May 24, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler