

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 8. W

Mackinac COUNTY

DESCRIPTION OF CORNER ~~Section corner common to Sections 8, 9, 16, 17~~ . . .

DESCRIPTION OF CORNER MONUMENT 1/2" x 36" Iron Bar buried in center of road

WITNESSES TO CORNER 6" B. Spruce N 42° W 52 Links . . .

4" Cedar S 80° W 37 1/2 Links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by proportionate measure to north and south and in center of N-S road.

Corner was placed and witnessed May 24, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 8/11/60