

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 8. W.

M a s k i n a c COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 4, 5, 8, 9. . . .

DESCRIPTION OF CORNER MONUMENT 1/2" x 36" Iron bar buried in center of road

WITNESSES TO CORNER 10" W. Spruce S 59° W 51 1/2 Links

10" Balsam N 50° W 52 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was re-established by proportionate measure to north and
south and in center of N-S road.

Corner was placed and witnessed May 24, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60
REGISTERED LAND SURVEYOR
Billy D. Buckler