## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinec Co.

SURVEYOR'S MICHIGAN REGISTRATION NO.\_\_\_

5 Corners.

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER		
٠	1. PUBLIC LAND SURVEY	. T. 44 N. R. 8 N.	L-4, M-4		
	2. PROPERTY CONTROLL- ING IN SECTION 12	# #.	16-Sec.12, 13-Sec.12 14-Sec.12		
	•				
	3. MISCELLANEOUS PROPERTY IN SECTION	,T \$., R \$.			
	4. LOT NO, RECORDED PLAT				
	5. PRIVATE CLAIMS	<del></del>		REGISTER OF DEEDS STAMP AND	
	- Billy D. Buckler		l	FILING NUMBER	
	I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-1, 1981, established,				
re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior,					
Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established					
as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a  Decree of a Court of law:					
A. Description of original monument and accessories and/or subsequent restoration:  L-4 Center Corner, Section 12, T44N R8W.					
16-Sec.12 East 1/16 Corner, on South side of Section 12. 13-Sec.12 Southeast 1/16 Corner of Section 12.					
M-4					
14-Sec.12 South 1/16 Corner, on East side of Section 12.					
•					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:					
L-4 Placed genter corner at computed intersection of lines connectting opposite 1/4 corners.					
16-Sec.12 Placed corner midway bet. Sec. Cor. to East and 1/4 Cor. to West. 13-Sec.12 Placed corner at intersection of lines quartering the SE Quarter Section.					
M-4 Corner placed midway and on line bet. two Section Corners.  14-Sec.12 Placed corner midway bet. Sec. Cor. to South and 1/4 Cor. to Morth.					
		•	.,,,		
		•	•		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  Placed 1" pipe with 4" slum. cap at all corners. Bearings:					
L-4 12" Cedar. N25 E. 42.6' & 16" Cedar. S88 E. 57.0' & 12" R. Maple. S20 E. 22.2'					
L-4 12" Ceder, N25 E, 42.6' & 16" Ceder, S88 E, 57.0' & 12" R. Maple, S20 E, 22.2' 16-Sec.12 12" Cherry, S27 W, 20.1' & 8" H. Maple, S20 E, 40.9' & 10" H. Maple, East, 35.9'. 13-Sec.12 8" Cherry, N84 W, 24.1' & 8" Cherry, N4 W, 9.1' & 10" H. Maple, S27 E, 25.4'. N-4 10" Ceder, S51 E, 34.0' & 6" Ceder, N32 W, 47.7' & 7" Spruce, S29 W, 26.5'.					
N-4 10" Cedar, S51°E, 34.0' & 6" Cedar, N32°W, 47.7' & 7" Spruce, S29°W, 26.5'.					
्र <b>।क=छ्ल</b> 	.12 )" Updar, S/y'W,	12.4' & 12" Gedar,	821°E, 32.1' & 5" Ce	der, N44°E, 19.2'.	
	4.	000		ATE OF AVICE	
	SIGNED BY Sill	y & Buch	DATE 7-13-	BILLY O 6	
	Billy D. K	· -		SURVEYOR &	
8887 / 6					
•		000 11		BUCKLER LAND	
SIGNED BY Silly & Suckles. DATE 8-11-81 GURVEYOR S					
Billy D. Buokler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887					
FOR STATE AND UNITED STATES AGENCIES:					
			DATE	-	
	APPROVED AND SIGNED BY_	CHIEF OF SURVEY PARTY	DATE		
APPROVED AND SIGNED BI					

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971