

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8-9W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 6-1

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 4-22-68

WITNESSES TO CORNER..... 11" Hard Maple (1/8 NBT) S60°W 39.0'



12" Hard Maple clump (1/8 NBT) N31°E 58.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor. Found iron pipe set on an old fence line (down) running north to Hendricks Quarry.

Corner lies 2 chs. north of a woods road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-18-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing