

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Lace & Mackinac COUNTY  
T 44-45N R 8-9W

DESCRIPTION OF CORNER Township corner, also a Sec. corner common to 6-1-36-31

CORNER MONUMENT 2" iron pipe in 8" concrete monument

DATE MONUMENT PLACED AND WITNESSED 4-1-68

WITNESSES TO CORNER..... 8" Hard Maple (NBT) N1°W 18.8°



8" Hard Maple (NBT) S60°W 20.0°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed this corner as set by unknown surveyor.  
Monument lies in line with roads to north and east.  
Fence corner is 33.0' west of corner.  
Found two 2" iron pipes, placed as witnesses, bearing N45°W 45.0° and S45°E 45.0°.  
Corner found by G. Wiggins and survey crew.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

DATE

3-18-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68