

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 8-9W

DESCRIPTION OF CORNER Sec. corner common to Secs. 18-19-13-24

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 2-27-69

WITNESSES TO CORNER..... 10" cedar (S13 NBT) N68°W 6.0'



12" cedar (S18 NBT) N50°E 5.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on Twp. line by single proportionate measure.

Found no evidence of original corner but did find a squared and notched post set by Marcus Schaaf, R.L.S. for a temporary marker, 11.0' west and 40' south of corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

4-21-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
✓ Forestry Div., Lansing

R 4047
Rev. 10/68