

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac & Luce COUNTY
T 44-45N R 9W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 1-2-35-36

CORNER MONUMENT 2" iron pipe in 8" concrete monument

DATE MONUMENT PLACED AND WITNESSED 5-9-68

WITNESSES TO CORNER..... 12" Hard Maple clump (S1 NBT) S8°E 55.8'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor.
Found monument and wood post in place.
Corner found by Survey crew while making retracement of area.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

3-14-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing