

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac & Luce COUNTY


T 44-45N R 9W

DESCRIPTION OF CORNER 1/2 Cor. bet. Secs. 2-35

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-26-68

WITNESSES TO CORNER..... 3" R. Pine (NBT) S30°E 16.6°



4" R. Pine (NBT) N45°E 46.3°

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. cors.
Found no evidence of original cor.

Cor. lies on west edge of a pine plantation.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-14-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68