

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Luce & Mackinac COUNTY


T 44-45N R 9W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-19-68

WITNESSES TO CORNER..... 12" W. Pine (NBT) N88°E 21.5'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 50' North of fence line.

This corner re-established midway and on line between two section corners.  
Found no evidence of original corner.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 3-14-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing