

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44N N.R. 9W


Mackinac COUNTY

DESCRIPTION OF CORNER West 1/16 corner bet. Secs. 2-35

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-28-68

WITNESSES TO CORNER..... 10" W. Pine (1/16 BT) S 53°E 13.7'



CIRCLE CORNER REGISTERED

6" Soft Maple (1/16 BT) N55°E 24.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to west and  $\frac{1}{4}$  cor. to east.

Corner lies 170' east of road.

*This is a corrected Copy*

*BDB*

*12/11/69*

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 3-17-69