

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 43-44N R 9W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 2-3-34-35

CORNER MONUMENT Iron fence post in N-S fence

DATE MONUMENT PLACED AND WITNESSED 8-27-68

WITNESSES TO CORNER..... 12" R. Pine (S2 NBT) S71°E 25.5'



14" R. Pine (S35 NBT) N60°E 41.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor. Found iron fence post and wood stake set in N-S fence line.

No evidence of original witnesses. Position checks with good corners in the area.

*this is a corrected copy*

*BDB 12/11/69.*

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

3-17-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
✓ Forestry Div., Lansing

R 4047  
Rev. 10/68