

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 9W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 1-2

CORNER MONUMENT 2" iron pipe in 8" concrete mon.

DATE MONUMENT PLACED AND WITNESSED 5-7-68

WITNESSES TO CORNER..... 14" hard maple (1/8 NBT) N82°W 14.6'



18" soft maple (1/8 NBT) S3°E 34.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor. Found no original evidence.
Corner found by C. Johnson, Instr. Man. Cor. lies 1 chain north of road.

SURVEYOR'S SEAL

SIGNED

Billy B. Buckler
Billy B. Buckler
REGISTERED LAND SURVEYOR

DATE

3-14-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68