

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 9W

DESCRIPTION OF CORNER 1/4 corner between Secs. 22-23

CORNER MONUMENT Iron fence post in N-S fence line

DATE MONUMENT PLACED AND WITNESSED 8-26-68

WITNESSES TO CORNER..... 10" Jack pine (1/8 NBT) N 72°E 41.7'



9" Red Pine " S50°E 44.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway bet. two Sec. Corners and on a N-S fence line.
Found no evidence of original Cor.

Cor. lies 40' west of road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

3-17-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68