


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac COUNTY
T 43-44N R 9W

DESCRIPTION OF CORNER ½ Cor. bet. Secs. 2-35
CORNER MONUMENT 1" pipe with 4" aluminum cap
DATE MONUMENT PLACED AND WITNESSED 8-28-68
WITNESSES TO CORNER..... 9" W. Pine (½S NBT) S80°W 34.7'



9" Tamarack (½S NBT) S34°E 8.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old squared wood post, set by unknown surveyor. Position checks well with corner ½ mile west.
Found remains of hemlock stump in vicinity but could identify none as the original witnesses.
Corner lies in wet swamp.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-17-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing