

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 44N R 9W

DESCRIPTION OF CORNER 1/4 Corner bet. Sections 23-24

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 3-21-69

WITNESSES TO CORNER..... None



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. cors. Found no evidence of original witnesses.

Corner lies in south margin of a small island, in an open bog.

SURVEYOR'S SEAL

Billy D. Buckler
Billy D. Buckler

SIGNED

REGISTERED LAND SURVEYOR

DATE

4-22-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68