

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44-45 N.R. 10 W


Mackinac and Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 6 and 31

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 11/3/60 with J. Halbach, D.F.

WITNESSES TO CORNER...15" Soft Maple (1/4" NBT) S 3° W 34 Links



13" Soft Maple (1/4" NBT) N 78° W 35 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by proportionate measure between two Section Corners.

No evidence of original corner. Corner lies 1/2 chain south of road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/23/61