

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44-45 N.R. 10W


Luce - Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 4-33

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 12-13-63 with Ed Eckhart, Assistant Forester

WITNESSES TO CORNER..... 11" Cedar (1/2 S NBT) N62°W 07 Lks.



7" Cedar (1/2 S NBT) S20°W 10 Lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was Re-established midway and on line between two Section Corners.  
Found no evidence of Original Corner.

**SURVEYOR'S SEAL**

SIGNED *Billy D. Buckler*  
BILLY D. BUCKLER  
REGISTERED LAND SURVEYOR

DATE 7/30/1964