

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Luce & Mackinac COUNTY


T 44 & 45N R 10W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 3-4-33-34

CORNER MONUMENT Iron pipe, buried in road

DATE MONUMENT PLACED AND WITNESSED 12-17-68

WITNESSES TO CORNER..... 2" iron pipe N45°W 45.2'



2" iron pipe S45°E 45.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Recorded corner as set by unknown surveyor.  
Found iron pipe buried in center of N-S road for corner, with two iron pipes placed  
as witnesses.

SURVEYOR'S SEAL

*Billy D. Buckler*  
Billy D. Buckler

SIGNED

REGISTERED LAND SURVEYOR

DATE

4-21-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing