

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce-Mackinac COUNTY


T 44-45N R 10W

DESCRIPTION OF CORNER 1/2 Cor. bet. Secs. 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 1-31-69

WITNESSES TO CORNER..... 22" W. Pine (1/8 NBT) S17°E 40.1'



6" W. Birch (1/8 NBT) N32°W 4.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner re-established midway and on line bet. two Sec. Cors.
Found no evidence of original Cor. Distance east to small pond checks.**

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

DATE

4-21-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68