

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44N N.R. 10W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 6-7

CORNER MONUMENT 1 1/2" x 30" iron pipe

DATE MONUMENT PLACED AND WITNESSED 10-31-69

WITNESSES TO CORNER..... 18" Hard Maple (1/8 NBT) N6°W 1.6°



12" Hard Maple (1/8 NBT) South 45.7°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in an old fence corner. Found remains of fence to East, West and North.

Distance to corners; 1/2 mile west and 1/2 mile East check wall.

Corner lies 20° South of road and in old fence line, grown in with trees.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 3-2-70
REGISTERED LAND SURVEYOR