

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44N N.R. 10-11W


Mackinac COUNTY

DESCRIPTION OF CORNER ½ Cor. bet. Secs. 7-12

CORNER MONUMENT 1 ½" x 30" iron pipe, buried in center of N-S road

DATE MONUMENT PLACED AND WITNESSED 10-31-69

WITNESSES TO CORNER..... 8" Elm (½S NBT) S83°E 16.8°



12" Elm (½S NBT) S52°W 19.9°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway bet. two Sec. Cors. and in approx. center of an old N-S road.

Found no evidence of any corner here.

Cor. lies 39.0' north of an old E-W railroad grade.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1-26-70
REGISTERED LAND SURVEYOR