

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44N N.R. 10W


Mackinac COUNTY

DESCRIPTION OF CORNER 4 Cor. bet. Secs . 7-18

CORNER MONUMENT Wood post

DATE MONUMENT PLACED AND WITNESSED 12-11-69

WITNESSES TO CORNER..... 13" Soft Maple (1/2 S NBT) N13°W 29.2'



14" Hard Maple (1/2 S NBT) S35°W 29.1'

14" Hard Maple (1/2 S NBT) S75°E 19.8'

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner placed on line and by single proportionate measure bet. two Section Corners.

Found no evidence of original corners.  
Corner lies in a hardwood timber type.

SURVEYOR'S SEAL

*Billy D. Buckler.*  
SIGNED Billy D. Buckler DATE 12-3-70  
REGISTERED LAND SURVEYOR