FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

1 Corner.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	т. <u>44 </u>	C-8	
2. PROPERTY CONTROLL- ING IN SECTION——	N. E. V. S., R W.		
3. MISCELLANEOUS PROPERTY IN SECTION.			
4. LOT NO, RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I,			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner set from 1 original ET, Cedar 6", N65°E, 18 lks. (11.88°). Corner lies in center of old North and South R.R. Grade.			
C. Description of monument for D.N.R. Monument. New 5" Cedar, S71°W, 23. 4" Cedar, S65°E, 27. 4" Cedar, N10°E, 30. Cedar Stump, N65°E,	Bearings: 4' 0' 9'	. 21	
David B. Babbi	tt	DATE4-21	
SURVEYOR'S MICHIGAN REG	ISTRATION NO.		(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

-8