

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44N N. R. 11W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 1-12

CORNER MONUMENT 1" pipe with 4" aluminum cap, buried in north edge of E-W road.

DATE MONUMENT PLACED AND WITNESSED 8-27-69

WITNESSES TO CORNER..... 14" Hard Maple (1/4 S NBT) S4° W 15.4'



14" Hard Maple (1/4 S NBT) N80° E 15.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway between two Sec. Cors.
Found 14" maple with old blazes on south edge of road with several trees blazed,
facing the corner location.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 3-6-70