

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 12 W

Mackinac COUNTY

DESCRIPTION OF CORNER West 1/8 corner between Sections 27 and 34

DESCRIPTION OF CORNER MONUMENT 2" x 36" Iron Pipe

WITNESSES TO CORNER 10" Yellow Birch (1/8 BT) S 53° E 3 Links

10" Hard Maple (1/8 BT) N 5° W 70 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway between Section corner 27, 28, 33, and 34 to west and 1/4 corner 27/34 to east. Corner lies 1/2 chain S. W. of road.

Corner was placed and witnessed August 29, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/29/60
REGISTERED LAND SURVEYOR
Billy D. Buckler