LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC CO.

3 CORNERS.

	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER		
	1. PUBLIC LAND SURVEY	_ T S., R W.			
	2. PROPERTY CONTROLL. 28	,T. 44 N. R. 12 W.	10, 15, 16	(8,00)	
	3. MISCELLANEOUS PROPERTY IN SECTION	,T S., R E.		8-370	
	4. LOT NO, RECORDED PLAT				
	5. PRIVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER				
	Gerald L. Wiggins 1, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970,				
	the corner points mentioned in lines 1 and 2 above were, in a field survey on				
10	A. Description of original monument and accessories and/or subsequent restoration: South 1/16 Corner on West side of Section 28. Not previously set.				
15	West 1/16 Corner South side of Section 28. Not previously set.				
16	East 1/16 Corner South side of Section 28. Not previously set.				
	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
10	Corner set midpoint on line between S.W. Corner and West 1/4 Corner of Section 28.				
15	Corner set midpoint on line between S.W. Corner and South 1/4 Corner of Section 28.				
16	Corner set midpoint on line between S.E. Corner and South 1/4 Corner of Section 28.				
DNR	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: DNR Monument set at all three corners.				
10	10" Cedar, S59°E, 12.5' 12" Cedar, N58°E, 19.7' 4" Cedar, N5°W, 20.2' 8" Cedar, S77°W, 12.3'	15 8" Cedar, S30 5" Cedar, S35 6" Cedar, N12 5" Cedar, N34	°E. 9.2' 10" M	. Birch, N24°E, 44.3' aple, N24°W, 28.4' eech, N68°W, 16.2' aple, S10°E, 24.5'	
	SIGNED BY SEPRITO L. NIG	lungains jins istration no 23521	DATE 6-14	B9 H WIGGINS LAND SURVEYOR No. 23521	
	FOR STATE AND UNITED ST	ATES AGENCIES:		FRED LAND S	
	SIGNED BY	CHIEF OF BURVEY PARTY	DATE		
	APPROVED AND SIGNED BY_	MICHIGAN REGISTERED L	DATEDATE	(SEAL)	
	SURVEYOR'S MICHIGAN REGISTRATION NO				