LAND CORNER RECORDATION CERTIFICATE

r.	Filing Requirement	t of Act 74, Mich. P.	A. 1970				
For corners in			,	7 - 11 /2 /2 11 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2	The state of the s	T) 'N 3	
MACOMB (County)	Located In: WARREN	Corner Code #	į	OF TO PINA REPORTO EL SUTON			
County	VVARREN			WAX 1 8 1999			
1. Public Land Survey T IN R 12E B-13 T R T R T R							
2. Property Controlling S	T R T R T R T R T R T R T R R T R T R R T		Regist	er of Deeds Sta	amp & File Ni	umber	
4. Lot No, Recorded Plat			A B C	DEFG	Н1 Ј К	L M	
5. Private Claims			2 6	5 4 4	3 1 2	\Box	
I, STEVEN E. DUNN, in a field do hereby certify that under requirements points mentioned in lines 1 and 2 above rules therefore as required in the current me Department of the Interior, Bureau of Land and /or that the corner points mentioned it with the rules of the Michigan Board of Lar established, re-established, monumente expressed below:	of P.A. 74, Michigan P.A. of were in conformance with ranual of survey instructions of Management or by a decree of lines 3, 4 and 5 above were and Surveyors or by a Decree of	1970, the corner regulations and the United States of a Court of Law in conformance fa Court of Law;	3 4 7 5 6 18 7 8 19	-17 16	1514	12 13 13 12 24 1	
NOTE: Not more than 2 corners, all in the same town and range, may be			10 30	29 28 2	27-26-	25—	
recorded on this certifica	te.		12 _31_	32 33 3	34-35	36_	
A. Description of original monument	and accessories and/or subse	equent restoration:	13				
GLO POST-NO EVIDENCE OF ORIGINA	AL CORNER FOUND. GLO	SURVEY PERFORMED E	BY JOSEPH FLET	TCHER-1816.			
	B. SOSNOWSKI EIGHT MIL & CO.'S WOODLAND SUB'			DEC. 2 MAR. 2	•		
MDOT RIGHT-OF-WAY MAPS: SHEETS 1 & 2				REV. 9-	-1981		
B. Description of corner evidence four B-13 SOUTH 1/4 CORNER	nd and/or method applied in	restoring or reestablishin	GBO	EPTED BY THE N UP AS THE OFFI LIC ACT 345 O	CIAL CORNER I F 1990 AT A	ひなひによ それぐい	
FOUND 4" BRASS CAP IN A MONUMEN	NT ROY IN ASPHALT CARR	DED CONCRETE BAVEN	ENT A	Jella E	DERBERG, P.S.,	CHATEMAN	
I VERIFIED THIS LOCATION BY COMP.						O(N)	
FIELD MEASUREMENTS & RECORD M B-13 TO A-13 B-13 TO 2647.18' FIELD 2622.	EASUREMENTS:			بديري	E OF MICA	Conn.	
ANGLE: 180°21'23" FIELD 180°21'00" MDOT	F			* 100	DUNN PROFESSIONAL SURVEYOR No. 28408	× 208 ×	
C. Description of monument for corner a	nd accessories established to	o perpetuate locating the	position of the co	orner:	ROFESSIONAL	errier.	
B-13 SOUTH 1/4 CORNER, T.1N., R I REPLACED THE BRASS CAP WITH A ACT 345 #28408" IN EXISTING MONUM	3/4" BY 24" IRON ROD WIT	Y TH 2" DIAMETER ALUMI	INUM CAP STAM	IPED *MACOMB	COUNTY MON	UMENT MI.	
<u>WITNESSES:</u> S.35°E. 54.17' FOUND "+" SCRI N.45°W. 48.23' FOUND PK NAIL S.5°W. 55.10' FOUND PK NAIL A S.28°E. 53.60' SET MAG NAIL A	. AND WASHER STAMPED AND WASHER STAMPED #	#14684 IN SW FACE OF #14684 IN EAST FACE O	UTILITY POLE FUTILITY POLE				
THE SELECTED LOCATION IS ACCEPT EVIDENCE OF THE POSITION OF THE	ED BY ME AND IS GENER. ORIGINAL CORNER.	ALLY ACCEPTED BY PR	ROFESSIONAL S	URVEYORS AS.	THE BEST AVA	NLABLE	
C	0865241 LIBER: ARMELLA SABAUG	08571 PAGE:79 H-MACOMB COU	92 09:29A NTY, MI R	01/21/19 EG/DEEDS	999		

878

28408

Signed by Steven E. D

Surveyor's Michigan License No.

Date Lept. 25, 1998