LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ξ	Marine Control of the
h.	MOTENTION

For corners in MAR 1.5 1999 Located In: Corner Code # **MACOMB** WARREN SECTION T 1N R 12E C-13 1. Public Land Survey T R R Ί 2. Property Controlling R Register of Deeds Stamp & File Number Т in Section 3. Miscellaneous Property in Sec. _, Recorded Plat 4. Lot No. 5. Private Claims JUNE 6, 1998. I, STEVEN E. DUNN, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points 5 mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as 6 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner 7 points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 8 Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 9 10 NOTE: Not more than 2 corners, all in the same town and 11 range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: GLO POST-NO EVIDENCE OF ORIGINAL CORNER FOUND. GLO SURVEY PERFORMED BY JOSEPH FLETCHER-1816 PLATS: MAR, 29, 1924 RAMM AND CO'S WOODLANDS SUB'N L.7, P.57 JUL. 21, 1936 SUPERVISOR'S PLAT NO. 4 SUPERVISOR'S PLAT OF BEHRENDT FARM SUPERVISOR'S PLAT OF MASCH FARMS L.17, P.28 SEP -??-1937 L.19, P.9 AUG. 8.1941 L.21, P.8 JAN. 8, 1943 SUPERVISOR'S PLAT OF WILLIAM REWOLDT SUBDIVISION 1.22 P.32 MAR. 2, 1956 FITZGERALD HEIGHTS SUBDIVISION L.35, P.29-31 C0865242 LIBER:08571 PAGE:793 09:29A 01/21/1999 MDOT RAW/ MAPS: SHEETS 1-3 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS L.C.R.C.: NOV. 30, 1993 L.26992, P.864 (W.C.R.) MARTIN C. DUNN #30081 SET WAYNE COUNTY REMONUMENTATION CORNER Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-13 SECTION CORNER, CORNER IS COMMON WITH C-1, TOWN 1 SOUTH, RANGE 12 EAST, WAYNE COUNTY. FOUND 1/2" IRON ROD WITH CAP #30081 IN A MONUMENT BOX IN ASPHALT CAPPED CONCETE PAVEMENT. I VERIFIED THE LOCATION BY COMPARING MEASURED DISTANCES AND ANGLES TO RECORDED DISTANCES AND ANGLES OF ITEMS LISTED STEVEN E. ABOVE, CORNER ALSO MATCHED 1 WITNESS TIE OF ABOVE L.C.R.C. OF MICHICAL OF STEVENE FIELD MEASUREMENTS & RECORD MEASUREMENTS: ANGLE B-13/C-13/D-13 C-13 TO D-13 C-13 TO B-13 178*49'00" PLATS 178*47'28" FIELD 2640.00' (GLO 40 CHAINS) 2639.38' FIELD 2640.00' (GLO 40 CHAINS) 2622.01' FIELD PROFESSIONAL SERVICE OF SURVEYOR SOLVEYOR NO. 28408 AND PROFESSIONAL P DUNN 2622.50' PLATS 2640.84' PLATS L.C.R.C. SET PK NAIL WITH W.C.R. WITNESS TAG IN POWER POLE. 292° AZ. 83.03' C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-13 SECTION CORNER I REPLACED THE FOUND 1/2" IRON ROD WITH CAP #30081 WITH A 3/4" BY 24" IRON WITH ALUMINUM CAP STAMPED "MACOMB COUNTY MONUMENT MI. ACT 345 #28408" IN EXISTING MONUMENT BOX. WITNESSES: N.67°W. FOUND PK AND WAYNE COUNTY REMON WITNESS TAG NE FACE UTULITY POLE. SET MAG NAIL W/MACOMB COUNTY REMON WITNESS TAG SE FACE UTILITY POLE. 83.01" N.44°E. 52.58' S.35°E. 62.68' FOUND 1/2" IRON ROD AT WEST END OF MEDIAN. 58.56 FOUND PK AND WASHER. THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. Date 10, 25, Signed by _ Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
REVISED MAY 14,1975 REVISED JAN., 1983

GROUP AS THE OFFICIAL CORNER UNDER MICHICAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 9/27/28

elser ê.

facluley WILLIAM E. SODERBERG, P.S., CHAIRMAN