SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in FEB 27 1997 Corner Code # **MACOMB** Located In: COMMISSION ERIN/LAKE TWP. (County) 1. Public Land Survey T_1N R_13E A-3 R T T R 2. Property Controlling T in Section Ţ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _, Recorded Plat 4. Lot No. 5. Private Claims C0438539 LIBER:07245 PAGE:400 08:59A 11/14/1996 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS in a field survey on MAY 4, 96 в do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 7 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of 20 Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan a Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, 10 recovered, found as expressed below: 30 11 NOTE: Not more than 2 corners, all in the same town and range, may be 12 recorded on this certificate. 13 A. Description of original monument and accessories and/or subsequent restoration: GLO POST-NO EVIDENCE OF ORIGINAL CORNER FOUND GLO ORIGINAL SURVEY PERFORMED BY WILLIAM PRESTON-1817 PLATS FRASER PARK SUBDIVISION VENETION VILLAGE GROVE WEST GROVE SUBDIVISION L.41 P 35-38 MAY 14, 1958 L.43 P. 39-41 APR. 3, 1959 ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON THE STATE OF T B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. WILLIAM E. SODERBERG, P.S., CHAIRMAN A-3 SECTION CORNER COMMON TO M-3.T.1N., R.12E. FOUND IRON ROD IN MONUMENT BOX IN CONCRETE PAVEMENT. ALSO FOUND IRON ROD I N MONUMENT BOX 1.63' NORTH. VERIFIED LOCATION OF CORRECT CORNER BY COMPARING MEASURED DISTANCES AND ANGLES ND ANGLES

ND ANGLES

STEVEN E.

DUNN

PROFESSIONAL

NO.

28408

STEVEN E.

ANGLES

NO.

A WITH RECORD DISTANCES AND ANGLES OF PLATS LISTED ABOVE. FIELD MEASUREMENTS AND RECORDED DISTANCES
A-3 TO A-2 2697.80°M. 40 CH (GLO 2640.00) 2697.80° R. (FRASER PARK SUB & TAX DESC.) A-3 TO A-4 2710.81'M 40 CH (GLO 2640.00) 2711.63 R. (WEST GROVE SUB.) A-3 TO B-3 2687.54 M ANGLE A-2/A-3/B-3 90°10'45" M. 90°09'00"R. (FRASER PARK SUB.) No. 28408
28408
28408
28408
28408 ANGLE B-3/A-3/A-4 89°59'13" M. 89°58'52" R. (WEST GROVE SUB.) C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-3 T.1N.R.13E. I REPLACED IRON ROD WITH 3/4"X24" IRON ROD WITH 2" DIAMETER ALUMINUM CAP STAMPED "MACOMB COUNTY MONUMENT, MI ACT345 #28408" IN AN EXISTING MONUMENT BOX WITNESSES FOUND IRON ROD IN MONUMENT BOX NORTH 1.63 SET P.K. NAII, W/MACOMB COUNTY REMONUMENTATION WITNESS TAG IN NE FACE UTILITY POLE N.43°W. 62.71 SET P.K. NAIL W/MACOMB COUNTY REMONUMENTATION WITNESS TAG IN SE FACE UTILITY POLE S.34°N. 70.221 SET P.K. NAIL W/MACOMB COUNTY REMONUMENTATION WITNESS TAG IN NE FACE UTILITY POLE N.45°E. 64.411 SET P.K. NAIL W/MACOMB COUNTY REMONUMENTATION WITNESS TAG IN NW FACE UTILITY POLE THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. Signed by Altern Date unn Surveyor's Michigan License No._ 28408