LAND CORNER RECORDATION CERTIFICATE

SURVEY & Filing Requirement of Act 74, Mich. P.A. 1970 REMONUMENTATION For corners in MACOMB Located In: Corner Code # APR 07 1998 ERIN (County) SECTION T IN R 13E B-11 1. Public Land Survey R Τ R Ί R T C0623802 LIBER:07784 PAGE:378 08:57A 12/22/1997 2. Property Controlling Т R R in Section T CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS 3. Miscellaneous T R Property in Sec. R Register of Deeds Stamp & File Number _, Recorded Plat 5. Private Claims GHIJKLM I, STEVEN E. DUNN, in a field survey on OCTOBER 14, 1997, .. 3 ------- 1 -do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules 9 --- 10 ---- 11 -- 12 --therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law 5 and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 15 - 14 6 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; 16 established, re-established, monumented, re-monumented, recovered, found as 7 expressed below: 8 23 -- 24 -9 NOTE: Not more than 2 corners, all in the same town and range, may be 10 27 ----- 25 ----- 25 ----.30 -28 recorded on this certificate. 1 12 A. Description of original monument and accessories and/or subsequent restoration: i GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND - ORIGINAL GLO SURVEY PERFORMED BY WILLIAM PRESTON 1817 PLATS: L. 2, P. 230 E.W. EYSTER SUBDIVISION NOV. 21, 1914 L. 3, P. 103 LISCOMB SUBDIVISION MAY 22, 1917 HALFWAY LITTLE FARMS AUG. 21, 1917 L. 3, P. 127 DEC. 01, 1919 L. 4, P. 7 HALFWAY CITY L. 4, P. 45 GEORGE FISCHER'S SUBDIVISION MAR. 30, 1920 PLEASANT RIDGE SUBDIVISION MAY 26, 1920 L. 4, P. 65 L. 4, P. 83 KEYS REALTY HALFWAY SMALL FARMS SUBDIVISION JUN 09, 1920 L. 4. P. 101 WILLIAM F. SCHULTZ SUBDIVISION AUG.18, 1920 CONTINUE ON BACK B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B - 11 FOUND IRON ROD IN MONUMENT BOX IN CONCETE PAVEMENT. I VERIFIED THE LOCATION OF THE FOUND IRON ROD BY COMPARING FIELD MEASUREMENTS TO RECORD MEASUREMENTS OF FOUND CORNERS OF PLATS LISTED ABOVE. FIELD MEASUREMENTS AND RECORD MEASUREMENTS: B-11 TO C-11 B-11 TO A-11 40 CHAINS OR 2640.00' GLO - 40 CHAINS OR 2640.00" PLATS - NORTH SIDE - 2725.78' PLATS - SOUTH SIDE - 2728.23' PLATS - NORTH SIDE - 2664.84' PLATS - SOUTH SIDE - 2664.68'. PLEASANT RIDGE SUB. 2727.75' FIELD - 2664.06' FIELD - 2727.48' ACCEPTED BY THE MACOMB COUNTY SURVEY PEER A-11/B-11/C-11

PLATS-176*46'00"

FIELD - 176*46'46"

C. Description of monument for corner and accessories established to perpetuate locating the position of the PATRICAL ESOPERBERG, P.S., CHAIRMAN

B-11, T. 1N., R. 13E. B - 11, T. 1N., R. 13E.

I REPLACED FOUND IRON ROD WITH A 3/4"X24" IRON ROD WITH A 2" DIAMETER ALUMINUM CAP STAMPED "MACOWS COUNTY MONUMENT MI. ACT 345" #28408 IN EXISTING MONUMENT BOX.

WITNESSES:

S. 66"W - 77.34" FOUND PK NAIL IN CONCRETE SIDEWALK JOINT.
S. 56"W - 59.25" FOUND 1/2" IRON ROD W/TRAV CAP #30092.
N. 56"W - 59.80" SE CORNER BRICK BUILDING "KEM - TEC" #16041 NINE MILE RD.
S. 71"W - 113.56" FOUND 1/2" IRON ROD.
SOUTH - B/C OF SOUTH SIDE OF NINE MILE ROAD.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BT PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Steven

Surveyor's Michigan License No.

28408

Signed by __

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983

Date 18, 1997

7 N)

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAÇOMB	Located In:	Corner Code #	
(County)	ERIN		
1. Public Land Survey	T <u>IN</u> R 13E T R	B-11	
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	T R T R S T R S T R S T R S T R S T R S T R S T R S T R S T R		
4. Lot No. Record	ded Plat		
I, STEVEN E. DUNN, in do hereby certify that under require points mentioned in lines 1 and 2 therefore as required in the current Department of the Interior. Bureau and for that the corner points ment the rules of the Michigan Board of	a field survey on OCTOBER rements of P.A. 74, Michigan P.A. of I above were in conformance with regat manual of survey instructions of the atof Land Management or by a decree stioned in lines 3, 4 and 5 above were in f Land Surveyors or by a Decree of a Comented, re-monumented, recovered,	14, 1997, 970, the corner ulations and rules United States of a Court of Law conformance with	√\$. .
NOTE: Not more than 2 c recorded on this c	corners, all in the same town a certificate.	nd range, may be	
A. Description of original mor	nument and accessories and/or subs	sequent restoration:	
CONTINUED FROM FRONT			·
L. 5, P. 1 L. 5, P. 3 L. 5, P. 58 L. 6, P. 68 L. 7, P. 12 L.10, P.74 L.22, P.16 L.22, P.17 L 23, P.42 L.37, P.44 L.38, P.29	MELROSE PARK SUBDIVISION HALFWAY CITY NO. 1 HENRY A STERNBERGER SUBD SCHEUREN AND MOK SUBDIVIS LOGACRES SUBDIVISION NO. 1 CLARK'S SUBDIVISION A.P. #13 A.P. #14 MERTZ SUBDIVISION CHUD & SOSKIN SUBDIVISION NA.P. #29	SION	SEPT. 09, 1920 SEPT. 10, 1920 SEPT. 10, 1921 JUNE 23, 1923 SEPT. 12, 1923 MAY 22, 1926 MAY 16, 1942 MAY 23, 1942 SEPT.20, 1946 OCT. 28, 1956 JAN. 09, 1957

I.D.O.T. RIGHT-OF-WAY MAP SHEET 85 SEPT. 1981

For corners in