LAND CORNER RECORDATION CERTIFICATE SURVEY & Filing Requirement of Act 74, Mich. P.A. 1970 REMONUMENTATION For corners in MACOMB Located In: Corner Code # APR 0 7 1998 ERIN SECTION 1N R 13E C-11 1. Public Land Survey Τ T R T R 2. Property Controlling T R C0623804 LIBER:07784 PAGE:381 08:57A 12/22/1997 F in Section S Т CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS 3. Miscellaneous F Property in Sec. R Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims D F F HIJKLM G I, STEVEN E. DUNN, in a field survey on OCTOBER 14, 1997, 2 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner 3 points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law 12 5 and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 6 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 7 expressed below: 8 19 20 - 23 -9 NOTE: Not more than 2 corners, all in the same town and range, may be 10 28 -26recorded on this certificate. 1 1 12 -- 35 A. Description of original monument and accessories and/or subsequent restoration: 33 -34 -..36 ... .31. 13 GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND. ORIGINAL SURVEY PERFORMED BY WILLIAM PRESTON - 1817 PLATS: L. 2, P. 230 E.W. EYSTER SUB. NOV. 21, 1914 L. 3, P. 103 LISCOMB PLAT MAY 22, 1917 L. 4, P. 7 HALFWAY CITY DEC. 01, 1919 L. 4, P. 67 PLEASANT RIDGE SUB. MAY 26, 1920 L. 4, P. 83 KEY'S HALFWAY SMALL FARMS SUB. JUN. 09, 1920 L. 4, P. 101 WILLIAM F. SCHULTZ SUB. AUG. 18, 1920 SEPT. 09, 1920 SEPT. 10, 1920 MELROSE PARK SUB. L. 5, P. 1 L. 5, P. 3 HALFWAY CITY SUB. NO. 1 L. 6, P. 68 SCHUEREN AND MOK SUB. JUN. 23, 1923 L. 7, P. 12 LONGACRES SUB. NO. 1 SEPT. 12, 1923 L. 10, P. 74 CLARKS SUB. MAY 22, 1926 L. 22, P. 16 L. 37, P. 44 A P #13 MAY 16, 1942 CHUD & SOSKIN SUBD'N, NO. 1 OCT. 02, 1956 L. 38, P. 29 A.P. #29 JAN. 09, 1957 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-11 FOUND 1/2" IRON IN MONUMENT BOX IN CONCRETE PAVEMENT. I VERIFIED LOCATION OF FOUND IRON BY COMPARING FIELD MEASUREMENTS TO RECORD MEASUREMENTS OF CORNERS FOUND IN ABOVE PLATS. CORNER IS AT SOUTH LINE OF LEFT TURN LANE OF 9 MILE ROAD. AND 38.9' EAST OF CENTERLINE OF CUSHING ROAD. ACCEPTED BY THE MACOMB COUNTY SURVEY PEER FIELD MEASUREMENTS AND RECORD MEASUREMENTS: GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN C-11 TO B-11 C-11 TO C-12 OF 1990 AT A MEETING HELD BUBLIC GLO - 40 CHAINS (2640.00') GLO - 40 CHAINS (2640.00) ΩN PLATS NORTH SIDE - 2725.78 FIELD - 2661.941 PLATS SOUTH SIDE - 2728.231 RBERG, P.S., CHAIRMAN FIELD 2727.48 C.. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C - 11 T. 1N., R. 13E DUNN I REPLACED FOUND 1/2" IRON ROD WITH A 3/4" X 24" IRON ROD WITH A 2" DIAMETER ALUMINUM CAP STAMPED "MACOMB COUNTY MONUMENT MI. ACT 345" #28408 IN EXISTING MONUMENT BOX. WITNESSES:

S. 76°W. 73.80' NE CORNER OF CATCH BASIN CASTING.
N. 61°W. 79.55' SE CORNER OF CATCH BASIN CASTING.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE

SET MAG NAIL & MCR WITNESS TAG IN WEST FACE OF UTILITY POLE.

SET MAG NAIL & MCR WITNESS TAG IN EAST FACE OF UTILITY POLE.

NORTH 38 43'

SOUTH 28.10'

EVIDENCE OF THE ORIGINAL CORNER.

Signed by <u>Itemse</u> E. Dumn

Surveyor's Michigan License No. 28408

Date Dec. 18, 19, 97