REMONUMENTATION SUHVEIL

APR 2 9 1996

Signed by Mandy
Surveyor's Michigan License No.

COMMISSION CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS

_		, E 40 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			CORDATION CERT of Act 74, Mich. P.A		•					
For	corners in	•				1						
	MACOM (Cor	B unty)	Located in: Sterlir Towns		rner Code #		• •					
1.	Public Land	d Survey	T_2N_ R_12E T R T R			GF PL ON	ROUP AS JBLIC A	THE OF	OF 199	ORNEH O AT	เบทบ	SURVEY PE ER MICHIG ETING HE
	Property Co in Section Miscellaneo	s ous s	T R	·			W- <i>yE</i> WIL	LIAM E.S	ODERBE			
	Property in	Sec. S	TR	· <u></u>			· -					
4. 5.	Lot No Private Clai	, Records	ed Plat				A E	9 C D	E F	G H	1 .	KLN
••							2		ĬŢ.] 3-		
							3				$+$ $\overline{+}$	
l, do_b	Randy Kol	<u>ehouse</u> , in a	a field survey on ments of P.A. 74 Mic	June 20	of 1970, the corner	95 ,	'				+-1	ı——ı2—
ment in the Lanc	tioned in line e current ma I Managemei	s 1 and 2 above were inual of survey instruc nt or by a decree of a	in conformance with rections of the United Stat Court of Law and/or the with the rules of the Mic	gulations ar es Departm at the come	nd rules therefore as re ent of the interior, Bu r points mentioned in I	equired reau of lines 3,	5 - 1	B 17-	16-	15-		13
Decr	ee of a Cou das express	urt of Law; establish	ned, re-established, mo	numented,	re-monumented, reco	overed,		20	21	22-	23	24-
NOT	•		all in the same town	and range	. may be recorded		10 3	29-	28	27-	26	25
		s certificate.			,, ,		11			++		
A.	Description	on of original monu	ment and accessories	and/or su	ıbsequent restoratio	on:	133	32-	33-	34	35	36
B-5	1817	G.L.O. Notes	Wamp	ler	N/A		t Post					
	1960 1973	M.C.R.C. File	N/A		N/A		Pipe	1-11				
	1973	Cert. Survey L. 245 L.C.R.C. L. 2380 P			#33597 #17631		d. P.K. N d. P.K. N		nhalt			
	1977	L.C.R.C. L. 2886 P			#17631 #17631		d. 1/2" li					
	1989	L.C.R.C. L. 4723 P			#21563		d. 1/2" re	•		Box		
	1993	L.C.R.C. L. 5775 P		avermaat	#33988		d. 1/2" lr					
В.	Description	on of corner eviden	ce found and/or meth	od applied	l in restoring or rees	stablishin	g corne	r:				
B-5	Found boat spike in monument box on the center line of 18 Mile Road pavement running E-W and on fence line running South which checks Villager Sub. No. 2 & Pine Brook Sub. and the following witnesses.											
	L.C.R.C. L. 2380 P. 492 P.K. Nail in utility pole S.E.'ly 122.35 ft. L.C.R.C. L. 2886 P. 439 P.K. nail in utility pole SE'ly 122.27 ft.			L.C.R.C. L. 4723 P. 606 Az 120 degrees 66.81 feet P.K. nail in North face of 14" tree Az 197 degrees 29.00 feet P.K. nail with R.J.D. flasher in East face of U. Pole								
				L.C.R.C. L. 5775 P. 921 Az 120 degrees 66.81 feet P.K. nail in North face of 14" tree Az 197 degrees 29.00 feet P.K. nail with R.J.D. washer in East face of util pole Az 287 degrees 132.15 feet P.K. nail in guy pole								
	Measure I Measure I	E 2479.74 to C-5 (Vil W 2655.70 to A-5 (Pi	llager Sub. No. 2 = 247 ine Brook Sub. = 2655	'9.59) (G.L .50) (G.L.O	O. 2640.0) . 2655.84)							-
O.	Description	on of monument for	corner and accessor	ies establis	shed to perpetuate I	locating t	he posi	tion of t	he cor	ner:		
3-5	l replaced MI Act 34	the found boat spik 5 #25854" in an exist	e with a 3/4" x 24" iron ting monument box.	rod w/2" d	liameter aluminum ca	ap stamp	ed "Mac	omb Co	unty M	onume	nt	
	Nail	and Macomb Co. Pa	emon Tag in E Side B	Pole 9 100	∘ W se oo'				30.00	OF A	Alok	و و در
	Nail	Nail and Macomb Co. Remon. Tag in E Side P. Pole S 18° W 28.99' Nail and Macomb Co. Remon. Tag in S Side Guy Pole N 70° W 132.01'								*****	•••	Ga .
	Nail	Nail and Macomb Co. Remon. Tag in SW Side P. Pole S 72° E 122.60'						3	૾ૺઌ _{ૻ૽} ૾૽	RAND		1.1
			emon. Tag in NE Side					11101.1	*	KOLEHI LAN SURYO	ďρ	
	The select	ted location is accept	ted by me and is gene of the position of the o	rally accep	ted by professional s	urveyors			6.	258	۵.	0.3
	,		or the bosinou of the c	mgmai con	1 5 (.	/	7/11	in	** CASO	DIAN	o sur	es is rei
Signe	ed by	county of	forejean	<u> </u>	Date		141	19		*****	*****	,»*