

APR 2 9 1996

COMMISSION

## C0257458 LIBER:06779 PAGE:632 03:43P 10/03/1995 CARMELLA SABAUGH-MACOMB\_COUNTY, MI REG/DEEDS

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in					1											
MACOMB (County)			Located	in: Sterling Township	Corner Code	Corner Code #											
1. Public Land Survey		Т	R_12E .	<u>C-7</u>	<u>C-7</u>								• •				
		•														•	
			\$ T	R	<del></del>												
			3 T	R		<del></del>			_								
3.			S T	_ R			Regist	er of	Deed	s Stan	np &	File	Num	ber			
	Property in	n Sec.	3 T	. R												_	
		, Rec					_										
5.	Private Cla	aims	· · · · · · · · · · · · · · · · · · ·				_	A B	Ç .	D E	F G	H	1 .	J K		- 1	
	•						2	L¦ ↓		5	4	i		2			
					,		3										
	Daniel (C	. ! . !			••	40 05				<u> </u>	]	Ţ					
ا		olehouse . ify that under req							丁	,	Ï	10 		"	—12 	_	
		illy that under requires 1 and 2 above v	d		$\dashv$							_					
		nanual of survey in		-10		7-	16	— 1 <sub>5</sub> 5—	1	4	— із	_					
		ent or by a decree						-	+		+			$\vdash$	-		
4 ar	nd 5 above	were in conforman	ce with the rules	of the Michiga	n Board of Land S	Surveyors or by	а в	19		20	21	—22—	<u> </u>	3	24		
		ourt of Law; esta	blished, re-estat	olished, monum	ented, re-monum	ented, recovered	ıl, "										
found as expressed below:							10		١.			_	١.	[			
NO.	ΓE: Not ι	more than 4 corn		ΙÏ	T-	Ĭ	1		T	ľΠ	25						
	on th	nis certificate.					. 11										
							12	31	一一	2	33	34		5-	36	$\neg$	
A.	Descrip	tion of original m	onument and a	ccessories and	d/or subsequent	restoration:	13	ш		Ll	L					!	
C-7	1817	G.L.O. Notes		Wampler N/A			Set Post										
	1972	L,C.R.C. L, 234	46 P. 631	Patterson		#17631	1/2" Iron										
	1972	Cert, Survey L	. 2358 P. 928	Cantrell		#5782	N/A										
	1976	Cert. Survey L	. 2717 P. 311	Avey		#15396	N/A										
	1979 Cert. Survey L. 3089 P. 9			Soderberg #17635 Iron in Mon. Box													
	1979	L.C.R.C. L. 308	89 P. 943	Soderberg		#17635	Iron in Mon. Box										
	1993	Sterling Height	s Road Plans	Hubbell, R	oth & Clark	ark N/A 1/2" Rod in Mon. Box											
_	Dagarin	Man of a company cont															

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- C-7 Found a 5/8" rebar in a monument box at the center line intersection of Ryan and 17 Mile Roads. All witnesses from above L.C.R.C. have been destroyed. Checked witness of Sterling Heights Road Plans.

Sterling Heights Road Plans NE Cor. Conc. Sign Base S 43° W 108.91 "+" in Conc. Tele. Pad N 48° W 142.87'

Measure W 2644.42 to B-7 (Road Plans = 2644.42) (G.L.O. 2640.0) Measure E 2670.12 to D-7 (Road Plans = 2670.04) (G.L.O. 2647.26) Measure N 2634.57 to C-6 (G.L.O. 2640.0)

ACCEPTED BY THE MACOMB COUNTY SURVEY PEEL GROUP AS THE OFFICIAL CORNER UNDER MICHIGAL PUBLIC ACT 345 OF 1990 AT A MEETING HELI ON

WILLIAM E. SODERBERG, P.S., CHAIRMAN

OF

RANDY J.

KOLEHOUSE

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-7 I replaced the found 5/8" rebar with a 3/4" x 24" iron rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #25854" in an existing monument box.

NE Cor. Conc. Sign Base S 43° W 108.91 "+" in Conc. Tele. Pad N 48° W 142.87'

Nail and Macomb Co. Remon. Tag in NE Face P. Pole N 50° W 88.74'

Nail and Macomb Co. Remon. Tag in SE Face P. Pole S 50° W 66.85'

Nail and Macomb Co. Remon. Tag in N Face P. Pole S 40° E 68.52'

Nail and Macomb Co. Remon. Tag in W Face P. Pole N 50° E 72.49'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

CAND SUR! Signed by\_ Date Surveyor's Michigan License No. 25854